BOAT TRAILER WINCH ADJUSTMENT



INCORRECT

WINCH OR WINCH HANDLE CONTACTS BOAT

WINCH ARM SHOULD POINT UPWARDS 25° - 45° ADJUST AS REQUIRED FOR PROPER FUNCTION (EVERY MODEL OF BOAT IS DIFFERENT)

